

Model	No. of Cyl.	Std. Bore x Stroke (mm)	Displ. (cc)	Bore Size (mm)	Wiseco Kit Part Number	Price Per Kit	Wiseco Piston Part No.	Price Per Piston
Exciter 440 1975-81 • Cast Iron Bore	2	68 x 59.6	433	Std. 0.50 1.00 1.50			2284M06800 2284M06850 2284M06900 2284M06950	\$87.33 (D0425) \$96.06 (D4675)
SS440 1980-85 • Cast Iron Bore	2	66 x 64	437	Std. 0.50 1.00 1.50			2309M06600 2309M06650 2309M06700 2309M06750	\$91.70 (D2055) \$100.87 (D2506)
SRX440, SSR440 1978-80 L/C <i>(Will not fit 1981 model)</i> • Chrome Bore • Sleeving or replating required for oversizes	2	68.5 x 59.6	439	Std. 0.50 1.00			2282M06850 2282M06900 2282M06950	\$87.33 (D0425) \$96.06 (D4675)
Mountain Lite 1997-99 Phazer Series 1984-98 Venture 1991-98 XL-V 1991-93 • Fan Cooled • Pro-Lite • Cast Iron Bore	2	72 x 59.6	485	Std. 0.25 0.50 1.00 1.50			2310M07200 2310M07225 2310M07250 2310M07300 2310M07350	\$101.08 (D5606) \$111.19 (D2766)
Phazer 500 Series 1999-01 Venture XL Touring 1999-00 • Fan Cooled • Pro-Lite • Cast Iron Bore	2	72 x 59.6	485	Std. 0.25 0.50 1.00 1.50			2310M07200 2310M07225 2310M07250 2310M07300 2310M07350	\$101.08 (D5606) \$111.19 (D2766)
Phazer Series 2007 ALL NEW Venture Lite 2007	2	77 x 53.6	499	Std.			TBA	
SX 500 R 2000-01 Venture 500 1999-01 V-Max 500 Series 1994-01 • Pro-Lite • Nikasil Bore	2	68 x 68	493	Std.			2356M06800	\$96.05 (D3675)
V-Max 540 LC 1983-89 • Pro-Lite • Chrome Bore • Sleeving or replating required for oversizes	2	73 x 64	535	Std. 0.50 1.00 1.50			2304M07300 2304M07350 2304M07400 2304M07450	\$105.90 (D4536) \$116.49 (D9896)
SRV 540 1980-91 VK540 1988-05 XL-V 1986-90 • Pro-Lite • Cast Iron Bore	2	73 x 64	535	Std. 0.25 0.50 1.00 1.50			2305M07300 2305M07325 2305M07350 2305M07400 2305M07450	\$101.08 (D5606) \$111.19 (D2766)
EX570 Exciter LC 1987-90 Exciter Deluxe 1989-90 Exciter II 1991-93 • Cast Iron Bore • Pro-Lite • Nikasil Bore • Sleeving or replating required for oversizes	2	73 x 68	569	Std. 0.50 1.00 1.50			2335M07300 2335M07350 2335M07400 2335M07450	\$103.03 (D2816) \$113.33 (D0086)
Mountain Max 600 1998-99 Venture 600 1998 V-Max 600 Series 1994-99 • Liquid Cooled • Pro-Lite • Nikasil Bore • Sleeving or replating required for oversizes	2	74.8 x 68	598	Std. 0.50			2388M07480 2388M07530	\$105.04 (D3036)

Repl Ring Set Part No.	Repl Piston Pin	Repl Retainer Clips	Top End Gasket Kit	Bottom End Gasket Kit w / Seals	Top End Bearing	Main Bearing L.H. PTO	Main Bearing L.H. Ctr.	Main Bearing R.H. Ctr.	Main Bearing R.H. Mag	Advanced Sleeve	LA Sleeve
2677CS 2697CS 2717CS 2736CS \$13.98 (D938)	S511 \$13.60 (D618)	CW18 \$2.00 (D021)			B1003 \$14.95 (D798)						
2598CD 2618CD 2638CD 2658CD \$27.95 (D7761)	S477 \$13.60 (D618)	CW18 \$2.00 (D021)	W5302 \$34.03 (D2402)		B1003 \$14.95 (D798)		B5031 SS440 1980-83	B5031 SS440 1980-83	B5031 SS440 1980-83		
2697CSM 2717CS 2736CS \$13.98 (D938)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)							B5032 SRX (all), SSR 1978	6005FA \$105.56 (D4336)	
2835CD 2844CD 2854CD 2874CD 2894CD \$27.95 (D7761)	S257 \$13.60 (D618)	CW18 \$2.00 (D021)	W5106 \$34.03 (D2402)	WB1143 \$18.29 (D7901)	B1003 \$14.95 (D798)	TBA	B5032 Phazer 1988-98 Venture	B5032 Phazer 1988-98 Venture	B5032 Phazer 1988-98 Venture	6017FA \$105.56 (D4336)	
2835CD 2844CD 2854CD 2874CD 2894CD \$27.95 (D7761)	S257 \$13.60 (D618)	CW18 \$2.00 (D021)	W5723 \$64.85 (D1983)	WB1135 \$10.79 (D746)	B1003 \$14.95 (D798)	TBA	B5032 Venture 1999-00	B5032 Venture 1999-00	B5032 Venture 1999-00	6063FA \$105.56 (D4336)	
TBA	TBA	TBA	TBA	TBA	TBA	TBA					
2677CD \$27.95 (D7761)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W5409 \$56.74 (D5043)	WB1136 \$16.32 (D979)	B1031 \$15.95 (D759)						
2874CDM 2894CD 2913CD 2933CD \$27.95 (D7761)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)		WB1137 \$20.18 (D1121)	B1023 \$14.95 (D798)	B5033	B5033	B5033	B5033	6006FA \$105.56 (D4336)	
2874CD 2884CD 2894CD 2913CD 2933TD CD: \$27.95 (D7761) TD: \$28.94 (D7371)	S512 \$13.60 (D618)	CW20 \$2.00 (D021)	W5108 \$48.27 (D6982)		B1023 \$14.95 (D798)	B5002 VK540	B5031 VK540 XL-V	B5031 VK540 XL-V	B5032 XL-V B5031 VK540		
2874CD 2894CD 2913CD 2933TD CD: \$27.95 (D7761) TD: \$28.94 (D7371)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W5109 \$47.03 (D2282)	WB1138 \$16.18 (D179)	B1023 \$14.95 (D798)	B5033					
2945TDW 2963TD \$28.94 (D7371)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W5551 \$56.71 (D3043)	WB1136 \$16.32 (D979)	B1023 \$14.95 (D798)	B5033 V-Max 600 1994-96	B5033 V-Max 600 1994-96	B5033 V-Max 600 1994-96	TBA		

Model	No. of Cyl.	Std. Bore x Stroke (mm)	Displ. (cc)	Bore Size (mm)	Wiseco Kit Part Number	Price Per Kit	Wiseco Piston Part No.	Price Per Piston
Mountain Max 600 2000-02 SX600 R 2000-02 SX Venom Series 2004-06 Venture 600 1999-06 V Max 600 Series 1999-02 • Pro-Lite • Nikasil Bore • Electra Coated	3	65 x 59.6	593	Std.			2440M06500	\$112.90 (D4776)
Mountain Max 700 1998-04 SX 700 R 2000-01 Venture 700 1998-03 V-Max 700 Series 1997-02 • Pro-Lite • Nikasil Bore	3	70.5 x 59.6	698	Std.			2385M07050	\$105.04 (D3036)
Mountain 700 1998 SRX 700 1998-02 • Pro-Lite • Nikasil Bore • Electra Coated	3	69 x 62	696 / 706 / 716	Std. 0.50 / 1.00			2397M06900 2397M06950 2397M07000	\$108.56 (D4156)
SX Viper Series 2002-04 SX Viper Mountain 2003-06 Venture 700 2004 • Pro-Lite • Nikasil bore	3	69 x 62	696	Std. 0.50 / 1.00			2397M06900 2397M06950 2397M07000	\$76.49 (D0954)
RX-1 Series 2003-05 RX-1 Mountain 2003-05 RX Warrior 2004-05 Apex Series 2006-07 Attack Series 2006-07 • 13:1 Compression • Nikasil Bore	4	74 x 58	998	Std.			4707M07400	\$137.37 (D2428)
Overbore to 1025cc RX-1 Series 2003-05 RX-1 Mountain 2003-05 RX Warrior 2004-05 Apex Series 2006-07 Attack Series 2006-07 • 12:1 Compression • Nikasil Bore • Cylinder boring and replating required	4	74 x 58	1025	1.00			4743M07500	\$143.61 (D7168)
RX-1 Series 2003-05 RX-1 Mountain 2003-05 RX Warrior 2004-05 Apex Series 2006-07 Attack Series 2006-07 • 10:1 Compression • Turbo/supercharge applications • Nikasil Bore	4	74 x 58	998	Std.			4808M07400	\$124.88 (D3947)
Overbore to 1025cc RX-1 Series 2003-05 RX-1 Mountain 2003-05 RX Warrior 2004-05 Apex Series 2006-07 Attack Series 2006-07 • 10:1 Compr. (Turbo/supercharge applications) • Nikasil Bore • Cylinder boring and replating required	4	74 x 58	1025	1.00			4808M07500	\$124.88 (D3947)
Nytro/Nytro ER 2006 RS Rage 2005-06 RS Vector Series 2005-07 RS Venture Series 2005-07 RS Vector Mountain Series 2005-07 VK Pro 2007 12.5:1 Compression • Plating required for overbore	3	79 x 66.2	973 / 1049	Std. 3.00			4893M07900 4893M08200	\$124.88 (D3947) \$137.37 (D2428)
Nytro/Nytro ER 2006 RS Rage 2005-06 RS Vector Series 2005-07 RS Venture Series 2005-07 RS Vector Mountain Series 2005-07 VK Pro 2007 9.5:1 Compression Turbo • Plating required for overbore	3	79 x 66.2	973 / 1049	Std. 3.00			4894M07900 4894M08200	\$151.11 (D7609) \$166.22 (D7399)

Repl Ring Set Part No.	Repl Piston Pin	Repl Retainer Clips	Top End Gasket Kit	Bottom End Gasket Kit w / Seals	Top End Bearing	Main Bearing L.H. PTO	Main Bearing L.H. Ctr.	Main Bearing R.H. Ctr.	Main Bearing R.H. Mag	Advanced Sleeve	LA Sleeve
6500KE \$16.95 (D7101)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W6205 \$68.09 (D6804)	WB1139 \$23.86 (D1341)							
2776CD \$27.95 (D7761)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W5548 \$68.09 (D6804)	WB1139 \$23.86 (D1341)	B1039 \$15.95 (D759)						
2717CD 2736CD 2756CD \$27.95 (D7761)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W5604 \$55.61 (D6333)	WB1140 \$26.36 (D1851)	B1039 \$15.95 (D759)					FL1239 \$95.20 (D2175)	
2717CD 2736CD 2756CD \$27.95 (D7761)	S423 \$13.60 (D618)	CW20 \$2.00 (D021)	W6097 \$94.22 (D3565)	WB1140 \$26.36 (D1851)	B1039 \$15.95 (D759)					FL1239 \$95.20 (D2175)	
2913XA \$29.95 (D7971)	S532 \$13.60 (D618)	CW17 \$2.00 (D021)	W6112 \$76.49 (D0954)								
2953XG \$27.95 (D7761)	S532 \$13.60 (D618)	CW17 \$2.00 (D021)	W6112 \$76.49 (D0954)								
2913XA \$29.95 (D7971)	S532 \$13.60 (D618)	CW17 \$2.00 (D021)	W6112 \$76.49 (D0954)								
2953XG \$27.95 (D7761)	S532 \$13.60 (D618)	CW17 \$2.00 (D021)	W6112 \$76.49 (D0954)								
3110XG 3228XG \$27.95 (D7761)	S597 \$13.60 (D618)	CW19 \$2.00 (D021)	W6112 \$76.49 (D0954)								
3110XG 3228XG \$27.95 (D7761)	S622 \$16.31 (D979)	CW19 \$2.00 (D021)	W6112 \$76.49 (D0954)								